

ROOF TOP CHILLER REPAIR BURNABY 2021

20' X 10' rooftop chiller repair for the leaking seam.

Surface prep to [SSPC-SP3](#).

Apply 6" Mastic Sealing Tape to the entire length of the seam. Heat the surface of the steel to enhance the mastic bond.

Apply 3 coats of [MOIST METAL GRIP](#)® with stripe coat along the Mastic Sealing Tape.

Application conditions: Confined Space




Stripe coat over Mastic Sealing Tape and 1st coat of **MOIST METAL GRIP**®



2nd Coat of MOIST METAL GRIP®



DFT (Dry Film Thickness Reading) after 2nd coat



Project Pictures courtesy of [J. Kerschbaumer Inc.](#)