

BC FERRY

2005



The Queen of Nanaimo of the BC Ferries fleet went through a major retrofit in 2005. The underside of the steel deck near the cafeteria and the inside surfaces of the bow tip are frequently exposed to high humidity causing the surfaces to corrode. **MOIST METAL GRIP**® was used to solve this problem.