


Tyson Foods - Wisconsin

July 2021

PROBLEM: This section of pipe with a maximum temperature of 200F \ 93C did not meet the OSHA standard of 140F \ 60C and represented a potential burn hazard to employees. In addition, it needed to be protected from the possibility of dripping oils.

SOLUTION: Insulate the pipe with 150 mils \ 3.8 mm DFT of [HSC® Coating](#) and top coat with [RUSTGRIP®](#) to protect from the dripping oils. It now meets OSHA standards. [BROCHURE](#).



PROJECT CREDITS:

Project Coordinator: Brice Wandyg - Engineer III - Hillshire Tyson Foods

Project Manager: John Walliser - Senior Specialized Coatings Consultant \ Project Manager
Phone: (708) 268-2354 john@eaglecoatings.com

Project Picture: Courtesy of the Contractor - Bob McCarthy of Bassett Mechanical