

PENINSULA SAFEWAY

July 2011

EPOXOTHERM®



Existing Problems, Mold and Mildew, Rust, condensation and puddling in Parkade



Rusting rebar causing cracking and spalling of concrete



killed mold and mildew with bleach and pressure washing



Rebar coated with **RUST GRIP**® then patched



Masking and first coat



Finish coat



Condensation before coating



Condensation after coating



ponding before coating



No ponding after coating

